

## CAMRAIL – RAILWAY - CAMEROON

Part of a railway sparking plug has been treated with ZINGA.

*Problem:* agressivity due to urine of passengers



Surface preparation :  
 HP cleaning  
 Sandblasting SA 2,5  
 $Rz = 114 - 50 = 64 \mu m$   
 System:  
 3 x 60  $\mu m$  ZINGA