

## Chichester Treatment Works

Coated in 2005

All steelwork was coated with Zinga @ 100  $\mu\text{m}$  DFT + Zingalufer @ 40  $\mu\text{m}$  DFT + 2 x 100  $\mu\text{m}$  DFT





**Stirring frame before coating**



**Stirring frame after coating**

