



Ref: EG-BR-MA-PI-TE-Salaam-EN-13/11/08

www.zinga.eu

EL SALAAM BRIDGE – EGYPT

The treatment of the El Salaam Bridge in Egypt, was part of the Bridge Maintenance Program in 2007. This bridge carries a gas pipeline of the Egyptian Natural Gas Company (**GASCO**).



n Natural Gas Co

caseo

Approval letter by **GASCO** stating that the job was completed with high efficiency under supervision of the Projects General Department.










www.zinga.eu

The bridge had suffered severe corrosion. Some pictures before the **ZINGA** application:



And pictures after the **ZINGA** application:



Surface preparation:	
Sandblasting SA 2,5	Rz 75 μm
Most critical areas ZINGA (airless spray)	2 x 60 μm DFT
Other areas	2 x 00 µm Dr 1
ZINGA (airless spray)	1 x 60 μm DFT

