


NEWARK MARINA BRIDGE - UNITED KINGDOM

These are pictures of the **Newark Marina Bridge** in the United Kingdom.
The bridge was blast-cleaned, Zinganised and painted in 1998.

7 years later, in 2005, an inspection was carried out.
The system that was used (**ZINGA** + single-pack polyurethane paint), was still in very good condition.



System:
Blasting to SA 2.5
ZINGA 1 x 60 µm DFT
single-pack polyurethane paint