

LIGHT POLES – TERMINAL KATOEN NATIE CUENCA DEL PLATA MONTEVIDEO – URUGUAY

On 3 June 2009 a test application was done at the KATOEN NATIE Terminal of Cuenca del Plata in Montevideo.

KATOEN NATIE decided to test **ZINGA** on one of their 20 years old light poles.

On the 30 October 2009 (after 5 months), the site was revisited, and no sign of any failure was noted (not even the parts that are more sensitive to corrosion).

Surface preparation:

- Mechanical wire brushing with copper brushes to remove zinc salts and corrosion, without polishing the surface.
- Washing the surface with water + 5% ammonia.
- Drying the surface with clothes



Surface preparation:
Copper brushes

ZINGA 2 x 60 µm DFT

